

2700-FM-BAQ0023 2/2015 pennsylvania DEPARTMENT OF ENVIRONMENTAL PROTECTION			INSPECTION REPORT		Commonwealth of Pennsylvania Department of Environmental Protection Air Quality Program		
Date(s) of Inspection: 3/27/24		TV ☐ SM ☐ NM ☐	PA ☐ GP ☐ MEGA ☐	Permit #(s): _____	Expiration Date: _____	Case #: _____	PF ID #: 868000
Company Name: Kingdom Provisions				Municipality: Plumstead Twp		County: BUCKS	
Plant Name: Same as above				Physical Location: Same as below		Federal ID — Plant Code #:	
Responsible Official: Ephraim Soltz Fns					Mailing Address: 5960 Durham Rd		
Title: Owner					Pipersville, PA 18947		
Phone #(s): 267-914-7430							
Mark (X) All Inspection Types That Apply To This Inspection:							
☐ Full Compliance Evaluation (FCE)	☐ Plan Approval Inspection	☐ File Review (FR)					
☐ Operating Permit Inspection (PI)	☐ Initial Permit Inspection (IPI)	☒ Complaint Inspection (CI)					
☐ Routine/Partial (RTPT)	☐ Follow-Up Inspection (Ref. Date: _____)	☐ Sample Collection (SC)					
☐ Minor Source(s) Inspection (RFD)	☐ Stack Test Observation	☐ Multi-Media Inspection (MM)					
☐ Other:	☐ Announced						
Annual Compliance Certification Received: ☐ YES ☐ NO ☒ N/A				Date Received:			
AIMS Report Received: ☐ YES ☐ NO ☒ N/A				Date Received:			
Mark (X) All Activities That Apply:							
☐ File Review	☒ Pre-Inspection Briefing	☒ Exit Interview/Briefing					
☒ Pre-Inspection Observations	☐ Check For New/Unreported Sources	☐ Sample(s) Collected					
☐ Visible Emissions Observations	☐ Verify Operation of CEMS	☐ Other					
Comments/Recommendations: Enforcement since last FCE ☐ Yes ☐ No (If yes, attach summary) I arrived on site at 9:55 AM to conduct a complaint inspection. Winds were NNE at 1 mph and it was 44°F and cloudy. I met with Amber and Brent Pressley who stated that they source a small amount of hair off of some of the animal carcasses after the majority of hair has been removed in the scalding tank, and this only takes place 1-2 times a week sometime between 7 AM-5:30 PM when USDA inspectors are on site. I plan to come out to observe this process when it is occurring. Amber We then walked to the back of the property and I observed that all the rendering bins were empty. Ms. Pressley stated that MOPAC is still down							
Compliance Status: ☒ In ☐ Out ☐ Pending ☐ Awaiting Co. Report				Needs a Follow-Up Inspection? ☐ Yes ☐ No			
Company Representative: Amber Pressley		Title: Plant manager		Signature: 		Date: 3/27/24	
DEP Representative: Jennifer Ramos-Buschmann		Title: AO Specialist		Signature: 		Date/Time: 3/27/24 10:55 AM	
This document is official notification that a representative of the Department of Environmental Protection, Air Quality Program, inspected the identified site. The findings of this inspection are shown above and on any attached pages, and may include violations uncovered during the inspection. Violations may also be discovered upon review of sample results or from any additional review of Department records. Notification will be forthcoming, if such violations are noted.							



INSPECTION REPORT

Continued

Commonwealth of Pennsylvania
Department of Environmental Protection
Air Quality Program

and not accepting rendering, so all of their rendering is placed in a large trailer and hauled off site at the end of every day. I observed rendering being dumped into the trailer with a backhoe during the inspection. I noted minor rendering odors in that area at that time and the odors were noted only in that area. I observed the former compost area and noted no composting taking place.

Company -- plant name:

Kingdom Provisions

Initials of representative interviewed:

AP

Date:

3/27/24

Page 2 of 2

Reviewed By _____

☐ White -- Site☐ Yellow -- District Office☐ Pink -- Regional Office